# REPORT OF DRINKING WATER SAMPLING FOR LEAD CONTENT:

# Lone Star Rangers RIPLEY COUNTY R-IV SCHOOL

PREPARED FOR:

RIPLEY COUNTY R-IV SCHOOL DISTRICT 3277 US HIGHWAY 160 WEST DONIPHAN, MO 63935-8901

PREPARED BY:

SEMO COMPLIANCE & REMEDIATION 3349 COUNTY ROAD 484 POPLAR BLUFF, MO 63901

**DECEMBER 2023** 

DOCUMENT TO BE RETAINED INDEFINITELY

## **TABLE OF CONTENTS**

Drinking Water Sampling for Lead Ripley County R-IV School District 3277 US Highway 160 W Doniphan, MO 63935

EXECUTIVE SUMMARY
CONCLUSION/RECOMMENDATIONS
APPENDIX ASample Location Mapping
APPENDIX BLaboratory Analysis
APPENDIX CCredentials

#### **EXECUTIVE SUMMARY**

SEMO COMPLIANCE performed lead testing of multiple drinking fountain water sources at the Campus of Ripley County R-IV located at 3277 US HIGHWAY 160 WEST in Doniphan, Missouri. The sampling was performed by trained and licensed personnel in accordance with USEPA, HUD, and State of Missouri Regulations and Guidelines.

All inspectors involved with sampling activities had EPA-approved training in Lead. Credentials for our firm and the inspector collecting the samples are included in Attachment C to this document.

All samples were collected on a "first draw" basis. "First draw" is achieved by allowing the water system to rest for at least eight hours prior to sampling in order to collect any existing debris or settlement within the sample. The intent of this sampling is to replicate "worst-case scenario" conditions. As such, ENPAQ inspectors met at the school to collect water samples before the systems were used by staff or students. The sampling was completed in accordance with the Missouri SB681 Get the Lead Out of Schools Drinking Water Act requirements. The Missouri SB681 Get the Lead Out of Schools Drinking Water Act.

Drinking water samples were collected from seventeen (17) different locations throughout Ripley County R-IV Campus during the sampling event. The water samples were collected from drinking fountains utilized for drinking activities at the campus. After sample collection, samples were immediately delivered to Teklab, Inc. located in Collinsville, Illinois following strict chain of custody procedures. Teklab is a NELAP-accredited and State of Missouri-licensed laboratory specializing in drinking water analysis. Detailed sampling locations and sample results are located in Attachment A and Attachment B of this report.

Any samples reported over 5.0 ppb should be re-sampled on an annual basis at a minimum.

#### CONCLUSION/RECOMMENDATIONS


At this time, Semo Compliance recommends that all water sources testing at 5.0 ppb or above be removed from service. These sources are subject to additional maintenance activities and remediation prior to use. Before being put back into service, it is recommended these sources be re-tested to confirm compliance with acceptable levels. The initial testing did not locate any water sources above the recommended level.

Although remediation is not required since all water sources are within the recommended levels, remediation would include decreasing lead concentrations below 5 parts per billion using methods such as replacement of plumbing, solder, fittings, or fixtures, installation of filters and filter devices, or other effective methods in accordance with Missouri SB681 Get the Lead Out of Schools Drinking Water Act.

Any sources above the recommended level will be subject to an ongoing maintenance program and re-testing at appropriate intervals. Any samples reported over 5.0 ppb should be re-sampled on an annual basis at a minimum. The testing did not locate any water sources above the recommended level and will not require re-testing.

Although no samples were identified above the action level, Semo Compliance recommends that all water sources run for at least thirty seconds prior to use as recommended by the USEPA.

# APPENDIX A SAMPLE LOCATION MAPPING



# APPENDIX B LABORATORY ANALYSIS



December 04, 2023

Matt Marshall Semo Compliance & Remediation 3349 County Road 484 Poplar Bluff, MO 63901

TEL: (574) 718-9812

FAX:

RE: Lonestar

Dear Matt Marshall:

TEKLAB, INC received 17 samples on 11/21/2023 10:20:00 AM for the analysis presented in the following report.

Samples are analyzed on an as received basis unless otherwise requested and documented. The sample results contained in this report relate only to the requested analytes of interest as directed on the chain of custody. NELAP accredited fields of testing are indicated by the letters NELAP under the Certification column. Unless otherwise documented within this report, Teklab Inc. analyzes samples utilizing the most current methods in compliance with 40CFR. All tests are performed in the Collinsville, IL laboratory unless otherwise noted in the Case Narrative.

All quality control criteria applicable to the test methods employed for this project have been satisfactorily met and are in accordance with NELAP except where noted. The following report shall not be reproduced, except in full, without the written approval of Teklab, Inc.

If you have any questions regarding these tests results, please feel free to call.

Sincerely,

Patrick Riley Project Manager

(618)344-1004 ex 44

patrickriley@teklabinc.com



Illinois 100226

Kansas E-10374

Louisiana 05002

Louisiana 05003

Oklahoma 9978

WorkOrder: 23111632



## **Report Contents**

http://www.teklabinc.com/

Client: Semo Compliance & Remediation Work Order: 23111632

Client Project: Lonestar Report Date: 04-Dec-23

#### This reporting package includes the following:

Cover Letter	1
Report Contents	2
Definitions	3
Case Narrative	5
Accreditations	6
Laboratory Results	7
Receiving Check List	8
Chain of Custody	Appended



#### **Definitions**

http://www.teklabinc.com/

Client: Semo Compliance & Remediation Work Order: 23111632

Client Project: Lonestar Report Date: 04-Dec-23

#### Abbr Definition

- \* Analytes on report marked with an asterisk are not NELAP accredited
- CCV Continuing calibration verification is a check of a standard to determine the state of calibration of an instrument between recalibration.
- CRQL A Client Requested Quantitation Limit is a reporting limit that varies according to customer request. The CRQL may not be less than the MDL.
  - DF Dilution factor is the dilution performed during analysis only and does not take into account any dilutions made during sample preparation. The reported result is final and includes all dilution factors.
  - DNI Did not ignite
- DUP Laboratory duplicate is a replicate aliquot prepared under the same laboratory conditions and independently analyzed to obtain a measure of precision.
- ICV Initial calibration verification is a check of a standard to determine the state of calibration of an instrument before sample analysis is initiated.
- IDPH IL Dept. of Public Health
- LCS Laboratory control sample is a sample matrix, free from the analytes of interest, spiked with verified known amounts of analytes and analyzed exactly like a sample to establish intra-laboratory or analyst specific precision and bias or to assess the performance of all or a portion of the measurement system.
- LCSD Laboratory control sample duplicate is a replicate laboratory control sample that is prepared and analyzed in order to determine the precision of the approved test method. The acceptable recovery range is listed in the QC Package (provided upon request).
- MBLK Method blank is a sample of a matrix similar to the batch of associated sample (when available) that is free from the analytes of interest and is processed simultaneously with and under the same conditions as samples through all steps of the analytical procedures, and in which no target analytes or interferences should present at concentrations that impact the analytical results for sample analyses.
- MDL "The method detection limit is defined as the minimum measured concentration of a substance that can be reported with 99% confidence that the measured concentration is distinguishable from method blank results."
- MS Matrix spike is an aliquot of matrix fortified (spiked) with known quantities of specific analytes that is subjected to the entire analytical procedures in order to determine the effect of the matrix on an approved test method's recovery system. The acceptable recovery range is listed in the QC Package (provided upon request).
- MSD Matrix spike duplicate means a replicate matrix spike that is prepared and analyzed in order to determine the precision of the approved test method. The acceptable recovery range is listed in the QC Package (provided upon request).
- MW Molecular weight
- NC Data is not acceptable for compliance purposes
- ND Not Detected at the Reporting Limit

#### NELAP NELAP Accredited

- PQL Practical quantitation limit means the lowest level that can be reliably achieved within specified limits of precision and accuracy during routine laboratory operation conditions.
- RL The reporting limit the lowest level that the data is displayed in the final report. The reporting limit may vary according to customer request or sample dilution. The reporting limit may not be less than the MDL.
- RPD Relative percent difference is a calculated difference between two recoveries (ie. MS/MSD). The acceptable recovery limit is listed in the QC Package (provided upon request).
- SPK The spike is a known mass of target analyte added to a blank sample or sub-sample; used to determine recovery deficiency or for other quality control purposes.
- Surr Surrogates are compounds which are similar to the analytes of interest in chemical composition and behavior in the analytical process, but which are not normally found in environmental samples.
- TIC Tentatively identified compound: Analytes tentatively identified in the sample by using a library search. Only results not in the calibration standard will be reported as tentatively identified compounds. Results for tentatively identified compounds that are not present in the calibration standard, but are assigned a specific chemical name based upon the library search, are calculated using total peak areas from reconstructed ion chromatograms and a response factor of one. The nearest Internal Standard is used for the calculation. The results of any TICs must be considered estimated, and are flagged with a "T". If the estimated result is above the calibration range it is flagged "ET"
- TNTC Too numerous to count ( > 200 CFU )



#### **Definitions**

http://www.teklabinc.com/

Client: Semo Compliance & Remediation Work Order: 23111632

Client Project: Lonestar Report Date: 04-Dec-23

#### Qualifiers

- # Unknown hydrocarbon
- C RL shown is a Client Requested Quantitation Limit
- H Holding times exceeded
- J Analyte detected below quantitation limits
- ND Not Detected at the Reporting Limit
- S Spike Recovery outside recovery limits
- X Value exceeds Maximum Contaminant Level

- B Analyte detected in associated Method Blank
- E Value above quantitation range
- I Associated internal standard was outside method criteria
- M Manual Integration used to determine area response
- R RPD outside accepted recovery limits
- T TIC(Tentatively identified compound)



#### Case Narrative

http://www.teklabinc.com/

Work Order: 23111632

Report Date: 04-Dec-23

Client: Semo Compliance & Remediation

Client Project: Lonestar

Cooler Receipt Temp: N/A °C

#### Locations

	Collinsville		Springfield	Kansas City						
Address	Address 5445 Horseshoe Lake Road		3920 Pintail Dr	Address	8421 Nieman Road					
	Collinsville, IL 62234-7425		Springfield, IL 62711-9415		Lenexa, KS 66214					
Phone	(618) 344-1004	Phone	(217) 698-1004	Phone	(913) 541-1998					
Fax	(618) 344-1005	Fax	(217) 698-1005	Fax	(913) 541-1998					
Email	jhriley@teklabinc.com	Email	KKlostermann@teklabinc.com	Email	jhriley@teklabinc.com					
	Collinsville Air		Chicago							
Address	5445 Horseshoe Lake Road	Address	1319 Butterfield Rd.							
	Collinsville, IL 62234-7425		Downers Grove, IL 60515							
Phone	(618) 344-1004	Phone	(630) 324-6855							
Fax	(618) 344-1005	Fax								
Email	EHurley@teklabinc.com	Email	arenner@teklabinc.com							



### Accreditations

#### http://www.teklabinc.com/

Client: Semo Compliance & Remediation

Work Order: 23111632

Client Project: Lonestar

Report Date: 04-Dec-23

State	Dept	Cert#	NELAP	Exp Date	Lab
Illinois	IEPA	100226	NELAP	1/31/2024	Collinsville
Kansas	KDHE	E-10374	NELAP	4/30/2024	Collinsville
Louisiana	LDEQ	05002	NELAP	6/30/2024	Collinsville
Louisiana	LDEQ	05003	NELAP	6/30/2024	Collinsville
Oklahoma	ODEQ	9978	NELAP	8/31/2024	Collinsville
Arkansas	ADEQ	88-0966		3/14/2024	Collinsville
Illinois	IDPH	17584		5/31/2025	Collinsville
Iowa	IDNR	430		6/1/2024	Collinsville
Kentucky	UST	0073		1/31/2024	Collinsville
Missouri	MDNR	00930		5/31/2023	Collinsville
Missouri	MDNR	930		1/31/2025	Collinsville



## **Laboratory Results**

http://www.teklabinc.com/

Client: Semo Compliance & Remediation

Work Order: 23111632

Client Project: Lonestar

Report Date: 04-Dec-23

Matrix: DRINKING WATER

Sample ID	Client Sample ID	Certification Qual	RL	Result	Units	DF	Date Analyzed	Date Collected							
EPA 600 4.1.4 Lead															
23111632-001	A A-1	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 16:37	11/17/2023 8:35							
23111632-002	A A-2	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 16:33	11/17/2023 8:37							
23111632-003/	A B-1	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 16:30	11/17/2023 8:10							
23111632-004	A B-2	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 16:15	11/17/2023 8:12							
23111632-005/	A B-3	NELAP	1.0	< 1.0	µg/L	1	11/29/2023 16:11	11/17/2023 8:14							
23111632-006/	A B-4	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 16:00	11/17/2023 8:16							
23111632-007/	A B-5	NELAP	1.0	< 1.0	µg/L	1	11/29/2023 15:57	11/17/2023 8:20							
23111632-008/	A B-6	NELAP	1.0	< 1.0	µg/L	1	11/29/2023 15:53	11/17/2023 8:22							
23111632-009/	A B-7	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 15:49	11/17/2023 8:25							
23111632-010	A B-8	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 15:46	11/17/2023 8:27							
23111632-011	A C-1	NELAP	1.0	< 1.0	µg/L	1	11/29/2023 15:42	11/17/2023 8:53							
23111632-012	A C-2	NELAP	1.0	1.1	μg/L	1	11/29/2023 15:27	11/17/2023 8:55							
23111632-013	A E-1	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 15:24	11/17/2023 8:51							
23111632-014	A E-2	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 15:20	11/17/2023 8:49							
23111632-015	₹ F-1	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 15:16	11/17/2023 8:43							
23111632-016	A F-2	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 15:05	11/17/2023 8:45							
23111632-017	A I-1	NELAP	1.0	< 1.0	μg/L	1	11/29/2023 15:02	11/17/2023 8:39							



## Receiving Check List

http://www.teklabinc.com/

Client: Semo Compliance & Remediation	Work (	Order: 23111632	
Client Project: Lonestar	Report	Date: 04-Dec-23	
Carrier: UPS  Completed by: On: 21-Nov-23 Amber Dilallo	Received E Reviewed On: 21-Nov-23	Iby: Fille Hope	ein)
Pages to follow: Chain of custody 2  Shipping container/cooler in good condition?  Type of thermal preservation? Chain of custody present? Chain of custody signed when relinquished and received? Chain of custody agrees with sample labels? Samples in proper container/bottle? Sample containers intact? Sufficient sample volume for indicated test? All samples received within holding time?	None V Yes V	0	Temp °C N/A Dry Ice □
Reported field parameters measured:  Container/Temp Blank temperature in compliance?  When thermal preservation is required, samples are compliant 0.1°C - 6.0°C, or when samples are received on ice the same	Field ☐ La Yes ☑ N nt with a temperature betw	b ☐ NA ☑ Io ☐	
Water – at least one vial per sample has zero headspace?	C FROM THE DETAILS OF THE PROPERTY OF THE PARTY OF THE PA	No VOA vials ✓	
Water - TOX containers have zero headspace?	503550 S	No TOX containers ✓	
Water - pH acceptable upon receipt?		NA 🗆	
NPDES/CWA TCN interferences checked/treated in the field?		NA ☑	
Any No responses m	nust be detailed below or	on the COC.	

Samples were checked for turbidity and then preserved with nitric acid upon arrival in the laboratory. - amberdilallo - 11/21/2023 11:38:19 AM

CHAIN OF CUSTODY

of

Work order # 23111632 TEKLAB, INC. 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005 pg.

Semo Compliance & Remediation  Samples on:     ICE     BLUE ICE     NO ICE   LTG#   C LTG#     Samples on:   ICE     BLUE ICE     NO ICE   LTG#     Says County Road 484     C LTG#     C LTG#   C LTG#     C LTG#   C LTG#     C LTG#	Poplar Bluff, MO 63901	arshall Phone: 573-7/8-7812	mattmarshall 1986@gmail.com Fax: Client Comments:	Are these samples known to be involved in litigation? If yes, a surcharge will apply \( \text{T}\) Yes \( \text{T}\) No  Are these samples known to be hazardous? If yes, include details of the hazard. \( \text{T}\) Yes \( \text{T}\) No  Are there any required reporting limits to be met on the requested analysis? If yes, please provide  limits in the comment section. \( \text{T}\) Yes \( \text{T}\) No	ne/Number Sample Collector's Name MATRIX INDICATE ANALYSIS REQUESTED	S	Billing Instructions # and Type of Containers B in S in	Lead dwate I Was dge oil g Wa eous MeO HCL H2SO NAO HCL H2SO UNPR	tter  ER  O4  H  .	A-1 11-17-23 8:35 AMX X X	A-2 11-17-23 8:37Amx	B-1 11-17-33 8:10 AM X X X	B-2 11-17-23 8:12am x X X	B-3 11-17-23 8:19pm X X X	B-41 11-17-23 8:16AM X X X	B-5 11-17-33 8:20 pm x X X X	25-71-11	11-17-23 G-25mm X X	11-17-23		U 11-20-23/12:00pm (JAMAD (UPS) 11/23	
Client: 3349 County Re	te / Zip	Contact: Matt Marshall	E-Mail: mattmarshall 1986@gm:	re these samples known to be involved in re these samples known to be hazardous are there any required reporting limits to builts in the comment section.	Project Name/Number	Lonestar	Results Requested  Standard 1-2 Day (100% Surcharge)		Lab Use Only Sample Identificatio	26111632, A-1		003 B-1		(00) 8-3	13-10 15-41	00) 8-5	00 g -6	7-8 Pac)	Ore B-8	Relinquished By	Mat Marshall	

The individual signing this agreement on behalf of the client, acknowledges that he/shë has read and understands the terms and conditions of this agreement, and that he/she has the authority to sign on behalf of the client. See www.teklabinc.com for terms and conditions.



84328

BottleOrder.

1	_
	ב
	)
F	
C	n
=	Ć
10110	3
L	L
	<b>D</b>
	Z
MI VII	Ī
J	Ē
(	ز

Work order # 331116.33

of

pg.

TEKLAB, INC. 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005

FOR LAB USE ONLY			INDICATE ANALYSIS REQUESTED													Date/Time	11/21/23 1020	
Samples on: 圖 iCE 圖 BLUE ICE 文 NO ICE Preserved in: 圖 LAB 圖 FIELD Lab Notes	Client Comments:		MATRIX INDICATE A	Sp	roui Decia Slu	/ Lead ndwat al Was udge Goil ng Wa	ste	×	X	×	X	×	×	X		Received By	(SAM) and (AS)	
Phone:	Fax:	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Please provide	Sample Collector's Name	Matt Marhell	# and Type of Containers	MeOUS NaHSI MeO HCL H2SC NaOI HNO UNPR	ER 04 H	8:53 pm X	8.55mx	11-1-23 8:51 Am X	-22 8-49 Am X	100		11-17-23 8:39 m X		Date/Time	11-20-23/ 12:02pm	
te .	mattmarsnalr1986@gmail.com	Are these samples known to be involved in litigation? If yes, a surcharge will apply Are these samples known to be hazardous? If yes, include details of the hazard. Are there any required reporting limits to be met on the requested analysis?. If yes limits in the comment section.	Project Name/Number		Requested B	3 Day (50% Surcharge)	Sample Identification	1 6-1 11-33	2-2 11-17-33	E-1	J E-2 11-17-22	5 F-1 11-17-23	F-2 11-17-23	7-1 11-17		Relinquished By	Met M	
Client: Address: City / State / Zip Contact:	E-Mail:	Are these san Are these san Are there any limits in the co	Proje	Lonzstar	Res	Officer of the state of the sta	Lab Use Only	ē	CO	503		015	70.	Ō			Mad	

The individual signing this agreement on behalf of the client, acknowledges that he/she has read and understands the terms and conditions of this agreement, and that he/she has the authority to sign on behalf of the client. See www.teklabinc.com for terms and conditions.



BottleOrder: 84328

# APPENDIX C CREDENTIALS

